

Name of Work:
Maintenance of Water
Supply Existing Borewells
at Bellahalli,
Thirumenahalli and
Chokkannahalli Village
Surrounding area in Ward
No. 05, Byatarayanapura
Sub Division

Log Books

Log Book					
Location: Belahalli main Road (Near double road)				Date: 30/10/21	
Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	30	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	-	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronxe bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.		
15	45	Pump Couping (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.		
28	30	Non – return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronxe, Beaing bush	Each	1	
38	45	Circillps	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia			
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		


 ಸಹಾಯಕ ಅಭಿಯಂತರರು
 ಮ.ದಿ.ವ.ಪ. ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

Chandrasekhar House Road.

Date: 3/16/21

Location:	Baba Nagar 4 th main 4 th cross 1 st block		
Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village Surrounding area in Ward No. 05, Byatarayanapura Sub Division			
			Remarks

item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	76	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	7	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	8	
8	45	Intermediate Piece (I.P) With IP Leaded Bronxe bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.		
15	45	Pump Couping (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	11	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non – return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronxe, Beaing bush	Each	1	
38	45	Circillps	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia			
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

~~ಹಾಸನ~~
ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಹ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

Chokkannahalli (geer shiva temple) ceedle.

Log Book

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village

Date: 11/11/21

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of fitting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	Each	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	6	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	Each	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	1	
40	440.00	Threading of GI Pipes 50mm Dia	No's	1	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

ಚಿಕ್ಕನಹಳ್ಳಿ (ಗೇರ ಶಿವಾ ದೇವಾಲಯ) ಕೇಡಲ್.

ಚಿಕ್ಕನಹಳ್ಳಿ (ಗೇರ ಶಿವಾ ದೇವಾಲಯ) ಕೇಡಲ್.

Baba nager and main Road Dead end.

Log Book

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village

Date: 26/11/21

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of fitting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	64	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	Each	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	Each	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	1	
40	440.00	Threading of GI Pipes 50mm Dia	No's	1	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

NOOR nagara right side cross Road near choulby

Log Book

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Date: 27/11/21

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	50	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	8	
8	45	Intermediate Piece (I.P) with IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.		
14	30	Pump shaft made out of stainless steel Centreless ground with key way (up to 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.		
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No.		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

27/11/21

Shivapura and cross near Shivatemple.

Log Book

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Date: 2/12/21

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) with IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (up to 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.		
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No.		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

2/12/21

Belahalli near Apartment.

Log Book

Date: 9/12/21

Location:

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkanahalli Village

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkanahalli Village

Date: 21/12/21

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2808	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	70	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bows	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	6	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Chokkanahalli layout near Venkata Rama Reddy house for

Log Book

Date: 21/12/21

Location:

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkanahalli Village

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkanahalli Village

Date: 21/12/21

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2808	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	56	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bows	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	11	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Chokkanahalli Gunda Thopi. (Campigerali).

Log Book

Date: 29/12/2018

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village

Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	46	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	6	
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rollor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	8	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRTV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunnmetal) Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No.		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

ಇದರ ಮೇಲೆ ಬರೆಯಬೇಕು ಎಂದು ಬರೆಯಿರಿ

Baharager and main and cross near Bhoothathu public school right side,

Log Book

Date: 08/01/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village

Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	76	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	6	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.		
19	30	Rollor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	1	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRTV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No.		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

ಇದರ ಮೇಲೆ ಬರೆಯಬೇಕು ಎಂದು ಬರೆಯಿರಿ

Thirumenahalli near lake.

Log Book

Location: Thirumenahalli and Chokkanahalli Village
Date: 11/01/22

Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village

Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	10	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.		
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

chokkanahalli layout near venkateswarama streety house behind.

Log Book

Location: Thirumenahalli and Chokkanahalli Village
Date: 13/01/22

Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village

Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	64	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	10	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	1	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Belahalli near masjid

Log Book

Date: 26/01/22

Location:

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkannahalli Village

Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	50	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	14	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	8	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRY) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Near nagappa main Road 3rd cross Near Elphort Ahmed House.

Log Book

Date: 27/02/22

Location:

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkannahalli Village

Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	10	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	14	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRY) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's	1	
42	45.00	Supplying and fixing MCB	No's		
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Mureshwasra nagara near R.O. plant

Log Book					Date: 15/02/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarajapur Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each	56	
2	45	Transportation of pumping machineries	No.		
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	12	
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centless ground with key way (upto 8 stages)	No.		
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.		
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Sameshwasra layout mureshwasra temple behind borewell - ①

Log Book					Date: 21/02/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarajapur Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each	70	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	10	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	6	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Babannagar and main and cross near bharathi
public school left side.

Location: Babannagar and main and cross near bharathi public school left side.					Log Book		Date: 25/03/22
Maintenance of water supply Existing borewells at Bellahalli, Thirumehalli and Chokkannahalli Village					Surrounding area in Ward No. 05, Byatayanapura Sub Division		
Item No	Approved Quantity	Description	Unit	used	Remarks		
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60			
2	45	Transportation of pumping machineries	No.	1			
3	7	Rewinding of Submersible Pump Sets 10 HP	No.				
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.				
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.				
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.				
7	140	Pump Bowls	No.	1			
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1			
9	45	Upper Flange	No.	1			
10	45	Lower Housing	No.	1			
11	90	Guide vane	No.	2			
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1			
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1			
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1			
15	45	Pump Coupling (Stainless Steel)	No.	1			
16	60	Stud and Nuts	Each				
17	30	Motor Base With Pin	Each	1			
18	30	Starter (with one year Guarantee)	No.	1			
19	30	Rotor (with one year Guarantee)	No.	1			
20	35	Carbon Housing	No.	1			
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1			
22	45	Oil Seal	No.	1			
23	45	Oil Seal Steel Bush	No.	1			
24	45	D.O Bearing	No.	1			
25	210	Steel Bush	No.	14			
26	20	Allen Screw	No.				
27	45	Pump Key (Stainless Steel)	No.	1			
28	30	Non - return valve (NRFV) assembly complete with rubber 'O' Ring	No.	1			
29	45	Cable Guard	No.	1			
30	45	Strainer	No.	1			
31	45	Brass Filler	No.	1			
32	45	Labour Chargesw (Over Hauling Only)	No.	1			
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1			
34	50	Lock Ring	Each				
35	45	Carbon Housing	Each	1			
36	45	Top Carbon/ferrodo padding	Each	1			
37	45	Bearing (Gummetal) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1			
38	45	Circclips	Each	1			
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3			
40	440.00	Threading of GI Pipes 50mm Dia	No's				
42	45.00	Supplying and fixing MCB	No's	1			
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's				

Thirumehalli Agalavara layout Mam road near Apartment.

Location: Thirumehalli Agalavara layout Mam road near Apartment.					Log Book		Date: 10/03/22
Maintenance of water supply Existing borewells at Bellahalli, Thirumehalli and Chokkannahalli Village					Surrounding area in Ward No. 05, Byatayanapura Sub Division		
Item No	Approved Quantity	Description	Unit	used	Remarks		
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	76			
2	45	Transportation of pumping machineries	No.	1			
3	7	Rewinding of Submersible Pump Sets 10 HP	No.				
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.				
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.				
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1			
7	140	Pump Bowls	No.				
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1			
9	45	Upper Flange	No.	1			
10	45	Lower Housing	No.	1			
11	90	Guide vane	No.	2			
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1			
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1			
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1			
15	45	Pump Coupling (Stainless Steel)	No.	1			
16	60	Stud and Nuts	Each				
17	30	Motor Base With Pin	Each	1			
18	30	Starter (with one year Guarantee)	No.	1			
19	30	Rotor (with one year Guarantee)	No.	1			
20	35	Carbon Housing	No.	1			
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1			
22	45	Oil Seal	No.	1			
23	45	Oil Seal Steel Bush	No.	1			
24	45	D.O Bearing	No.	1			
25	210	Steel Bush	No.	8			
26	20	Allen Screw	No.				
27	45	Pump Key (Stainless Steel)	No.	1			
28	30	Non - return valve (NRFV) assembly complete with rubber 'O' Ring	No.	1			
29	45	Cable Guard	No.	1			
30	45	Strainer	No.	1			
31	45	Brass Filler	No.	1			
32	45	Labour Chargesw (Over Hauling Only)	No.	1			
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1			
34	50	Lock Ring	Each	2			
35	45	Carbon Housing	Each	1			
36	45	Top Carbon/ferrodo padding	Each	1			
37	45	Bearing (Gummetal) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1			
38	45	Circclips	Each	1			
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3			
40	440.00	Threading of GI Pipes 50mm Dia	No's				
42	45.00	Supplying and fixing MCB	No's	1			
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's				

Belahalli near R.O. plant.

Log Book

Location:

Date: 16/03/22

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byaterayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	54	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (up to 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRTV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

ಶ್ರೀಮತಿ ಬಸವರಾಜ್

ಹಿರಿಯ ಕಾರ್ಯದರ್ಶಿ

Babannagara and stage near Rajanna Huse.

Log Book

Location:

Date: 21/03/22

Maintenance of water supply Existing borewells at Belahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byaterayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	40	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (up to 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	1	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRTV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's		
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

ಶ್ರೀಮತಿ ಬಸವರಾಜ್

ಹಿರಿಯ ಕಾರ್ಯದರ್ಶಿ

Kuneshhooa nagara 1st main 3rd cross

Log Book

Date: 26/03/22

Date: 04/04/22

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	76	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (up to 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	14	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrado padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	1	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

shivshankar layout 3rd cross.

Log Book

Date: 04/04/22

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	30	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	6	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (up to 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrado padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	1	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

Baba nagasa 4th main 4th cross.

Log Book					Date: 11/04/20
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village					
Surrounding area in Ward No. 05, Byatalayampura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	64	
2	45	Transportation of pumping machineries	No.		
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	6	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze-bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.		
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	8	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and painting	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze. Beaing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No.	10	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

ಇದರಲ್ಲಿ ಬಾಕಿ ಇರುವುದು 1000 ರೂ. ವರೆಗೆ

Langsten layout main Road near Babery.

Log Book					Date: 19/04/20
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village					
Surrounding area in Ward No. 05, Byatalayampura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	80	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	1	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and painting	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze. Beaing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No.	10	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

ಇದರಲ್ಲಿ ಬಾಕಿ ಇರುವುದು 1000 ರೂ. ವರೆಗೆ

Venadapatt 1st main and cross.

Log Book					Date: 8/6/2018
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumennahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	90	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.		
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia			
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

DMK layout and cross.

Log Book					Date: 03/05/2018
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumennahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	58	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	14	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia			
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Sameshuasa layout kameshuasa temple behind borewell-2

Log Book					Date: 11/05/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each	52	
2	45	Transportation of pumping machineries	No.		
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	8	
7	148	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	Each	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal) Cast Aluminium Bronze. Beaing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	15	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Babanaagesa 1st main near Hummariappa House.

Log Book					Date: 17/05/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each	84	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	8	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	8	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunnmetal) Centrifugal) Cast Aluminium Bronze. Beaing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	20	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Kutenpa nagara 4th cross Entrance.

Log Book					Date: 25/05/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	70	
2	45	Transportation of pumping machineries	No.		
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	6	
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (up to 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	Each	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	No.	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	10	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

BSF Gate near compound.

Log Book					Date: 21/06/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	90	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.	8	
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (up to 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	1	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	20	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Nara layout and cross Dead end.

Log Book

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village
 Date: 15/06/22

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	50	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber O Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	1	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No.	10	
42	45.00	Supplying and fixing MCB	No.	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No.	1	

Baba nagasa Bhoothali public school Grant.

Log Book

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village
 Date: 23/06/22

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	76	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	8	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber O Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circlips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No.	15	
42	45.00	Supplying and fixing MCB	No.	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No.	1	

Somesnucasa layout 1st main Road

Log Book

Date: 28/06/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village				
Surrounding area in Ward No. 05, Byatarayanapura Sub Division				
Item No	Approved Quantity	Description	Unit	used
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	52
2	45	Transportation of pumping machineres	No.	1
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	42
7	140	Pump Bowls	No.	1
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1
9	45	Upper Flange	No.	1
10	45	Lower Housing	No.	2
11	90	Guide vane	No.	1
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1
15	45	Pump Coupling (Stainless Steel)	No.	1
16	60	Stud and Nuts	Each	6
17	30	Motor Base With Pin	No.	1
18	30	Starter (with one year Guarantee)	No.	1
19	30	Rotor (with one year Guarantee)	No.	1
20	35	Carbon Housing	No.	1
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1
22	45	Oil Seal	No.	1
23	45	Oil Seal Steel Bush	No.	1
24	45	D.O Bearing	No.	1
25	210	Steel Bush	No.	1
26	20	Allen Screw	No.	1
27	45	Pump Key (Stainless Steel)	No.	1
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1
29	45	Cable Guard	No.	1
30	45	Strainer	No.	1
31	45	Brass Filler	No.	1
32	45	Labour Chargesw (Over Hauling Only)	No.	1
33	45	Re-erection charges of pumping machineres including overhauling and pointing	Each	1
34	50	Lock Ring	Each	1
35	45	Carbon Housing	Each	1
36	45	Top Carbon/Ferrodo padding	Each	1
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Beaing bush	Each	1
38	45	Circclips	Each	1
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3
40	440.00	Threading of GI Pipes 50mm Dia	No's	20
42	45.00	Supplying and fixing MCB	No's	1
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1

Neer Odagere main Road 3rd cross near Ravagulla

Atuse.

Log Book

Date: 07/07/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village				
Surrounding area in Ward No. 05, Byatarayanapura Sub Division				
Item No	Approved Quantity	Description	Unit	used
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	50
2	45	Transportation of pumping machineres	Each	1
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	
7	140	Pump Bowls	No.	4
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1
9	45	Upper Flange	No.	1
10	45	Lower Housing	No.	2
11	90	Guide vane	No.	1
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1
15	45	Pump Coupling (Stainless Steel)	No.	1
16	60	Stud and Nuts	Each	6
17	30	Motor Base With Pin	No.	1
18	30	Starter (with one year Guarantee)	No.	1
19	30	Rotor (with one year Guarantee)	No.	1
20	35	Carbon Housing	No.	1
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1
22	45	Oil Seal	No.	1
23	45	Oil Seal Steel Bush	No.	1
24	45	D.O Bearing	No.	1
25	210	Steel Bush	No.	1
26	20	Allen Screw	No.	1
27	45	Pump Key (Stainless Steel)	No.	1
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1
29	45	Cable Guard	No.	1
30	45	Strainer	No.	1
31	45	Brass Filler	No.	1
32	45	Labour Chargesw (Over Hauling Only)	No.	1
33	45	Re-erection charges of pumping machineres including overhauling and pointing	Each	1
34	50	Lock Ring	Each	1
35	45	Carbon Housing	Each	1
36	45	Top Carbon/Ferrodo padding	Each	1
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronze, Beaing bush	Each	1
38	45	Circclips	Each	1
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3
40	440.00	Threading of GI Pipes 50mm Dia	No's	20
42	45.00	Supplying and fixing MCB	No's	1
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1

Sannayapuram near burial ground

Log Book

Date: 15/07/20

Location:

Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	624	
2	45	Transportation of pumping machineries	No.	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	1	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	5	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.	1	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	6	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	20	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

சென்னை மாநகராட்சி
பொதுப்பணித்துறை
தண்ணீர் வழங்கல் பிரிவு

Babannagere 1st main and cross near Radha Krishna House.

Log Book

Date: 21/07/20

Location:

Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village
Surrounding area in Ward No. 05, Byatarayanapura Sub Division

Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	70	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	4	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circclips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia	No's	25	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

சென்னை மாநகராட்சி
பொதுப்பணித்துறை
தண்ணீர் வழங்கல் பிரிவு

Sannivasapuram near Hennama Temple.

Log Book					Date: 28/07/20
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	74	
2	45	Transportation of pumping machineries	No.		
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	8	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	8	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRFV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and painting	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetel) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circulips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia		90	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Ambedkar Nagar near samudhaya Bhavana.

Log Book					Date: 23/08/20
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	80	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	1	
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (IP) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	8	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	4	
26	20	Allen Screw	No.	1	
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRFV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and painting	Each	1	
34	50	Lock Ring	Each	2	
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetel) Centrifugal) Cast Aluminium Bronze, Bearing bush	Each	1	
38	45	Circulips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia		90	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Someswar layout and main. Dead end

Log Book					Date: 08/08/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byalayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each	62	
2	45	Transportation of pumping machineries	No.		
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	1	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.		
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.	1	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	2	
11	90	Guide vane	No.	1	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	3	
17	30	Motor Base With Pin	Each	1	
18	30	Starter (with one year Guarantee)	No.	1	
19	30	Rotor (with one year Guarantee)	No.	1	
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetel) Centrifugal Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia		15	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

Shri nagara 1st cross near mangalath house.

Log Book					Date: 14/08/22
Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village					
Surrounding area in Ward No. 05, Byalayanapura Sub Division					
Item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each	70	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Coupling (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each	2	
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	2	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	1	
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filler	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferrodo padding	Each	1	
37	45	Bearing (Gummetel) Centrifugal Cast Aluminium Bronze, Beaing bush	Each	1	
38	45	Circilips	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	2	
40	440.00	Threading of GI Pipes 50mm Dia		20	
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1	

M.S. Nagasa 1st main Road.

Log Book

Date: 28/08/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village				
Surrounding area in Ward No. 05, Byatarayanapura Sub Division				
Item No	Approved Quantity	Description	Unit	used
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	56
2	45	Transportation of pumping machineries	No.	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	
7	140	Pump Bowls	No.	1
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1
9	45	Upper Flange	No.	1
10	45	Lower Housing	No.	2
11	90	Guide vane	No.	1
12	45	Impeller Shell moulded with aluminium Bronze	No.	1
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1
15	45	Pump Coupling (Stainless Steel)	Each	1
16	60	Stud and Nuts	Each	1
17	30	Motor Base With Pin	No.	
18	30	Starter (with one year Guarantee)	No.	
19	30	Rotor (with one year Guarantee)	No.	
20	35	Carbon Housing	No.	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1
22	45	Oil Seal	No.	1
23	45	Oil Seal Steel Bush	No.	1
24	45	D.O Bearing	No.	1
25	210	Steel Bush	No.	8
26	20	Allen Screw	No.	1
27	45	Pump Key (Stainless Steel)	No.	1
28	30	Non - return valve (NRTV) assembly complete with rubber 'O' Ring	No.	
29	45	Cable Guard	No.	1
30	45	Strainer	No.	1
31	45	Brass Filler	No.	1
32	45	Labour Chargesw (Over Hauling Only)	No.	1
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1
34	50	Lock Ring	Each	
35	45	Carbon Housing	Each	1
36	45	Top Carbon/Ferrodo padding	Each	1
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bealing bush	Each	1
38	45	Circclips	Each	1
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3
40	440.00	Threading of GI Pipes 50mm Dia	No's	730
42	45.00	Supplying and fixing MCB	No's	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1

Balanagasa 2nd main. 2nd cross near Venkatesh house.

Log Book

Date: 28/08/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkanahalli Village				
Surrounding area in Ward No. 05, Byatarayanapura Sub Division				
Item No	Approved Quantity	Description	Unit	used
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60
2	45	Transportation of pumping machineries	Each	1
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	
7	140	Pump Bowls	No.	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	1
9	45	Upper Flange	No.	1
10	45	Lower Housing	No.	1
11	90	Guide vane	No.	2
12	45	Impeller Shell moulded with aluminium Bronze	No.	1
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1
15	45	Pump Coupling (Stainless Steel)	No.	1
16	60	Stud and Nuts	Each	1
17	30	Motor Base With Pin	Each	1
18	30	Starter (with one year Guarantee)	No.	
19	30	Rotor (with one year Guarantee)	No.	
20	35	Carbon Housing	No.	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1
22	45	Oil Seal	No.	1
23	45	Oil Seal Steel Bush	No.	1
24	45	D.O Bearing	No.	1
25	210	Steel Bush	No.	4
26	20	Allen Screw	No.	
27	45	Pump Key (Stainless Steel)	No.	1
28	30	Non - return valve (NRTV) assembly complete with rubber 'O' Ring	No.	
29	45	Cable Guard	No.	1
30	45	Strainer	No.	
31	45	Brass Filler	No.	1
32	45	Labour Chargesw (Over Hauling Only)	No.	1
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1
34	50	Lock Ring	Each	
35	45	Carbon Housing	Each	1
36	45	Top Carbon/Ferrodo padding	Each	1
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bealing bush	Each	1
38	45	Circclips	Each	1
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3
40	440.00	Threading of GI Pipes 50mm Dia	No's	730
42	45.00	Supplying and fixing MCB	No's	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	1

Near Nagasa main Road 5th cross near skanderi House.

Log Book

Date: 01/10/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village				
Item No	Approved Quantity	Description	Unit	used
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60
2	45	Transportation of pumping machineries	No.	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	
7	140	Pump Bowls	No.	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	
9	45	Upper Flange	No.	
10	45	Lower Housing	No.	
11	90	Guide vane	No.	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	
15	45	Pump Coupling (Stainless Steel)	No.	
16	60	Stud and Nuts	Each	
17	30	Motor Base With Pin	No.	
18	30	Starter (with one year Guarantee)	No.	
19	30	Rotor (with one year Guarantee)	No.	
20	35	Carbon Housing	No.	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	
22	45	Oil Seal	No.	
23	45	Oil Seal Steel Bush	No.	
24	45	D.O Bearing	No.	
25	210	Steel Bush	No.	
26	20	Allen Screw	No.	
27	45	Pump Key (Stainless Steel)	No.	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	
29	45	Cable Guard	No.	
30	45	Strainer	No.	
31	45	Brass Filter	No.	
32	45	Labour Chargesw (Over Hauling Only)	No.	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	
34	50	Lock Ring	Each	
35	45	Carbon Housing	Each	
36	45	Top Carbon/Ferodo padding	Each	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	
38	45	Circclips	Each	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	
42	440.00	Threading of GI Pipes 50mm Dia	No's	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	

somehwasa layout near Burial ground.

Log Book

Date: 01/10/2022

Location: Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village				
Item No	Approved Quantity	Description	Unit	used
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	58
2	45	Transportation of pumping machineries	Each	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.	
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.	
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.	
7	140	Pump Bowls	No.	
8	45	Intermediate Piece (I.P) With IP Leaded Bronze bush	No.	
9	45	Upper Flange	No.	
10	45	Lower Housing	No.	
11	90	Guide vane	No.	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	
14	30	Pump shaft made out of stainless steel Centrefless ground with key way (upto 8 stages)	No.	
15	45	Pump Coupling (Stainless Steel)	No.	
16	60	Stud and Nuts	Each	
17	30	Motor Base With Pin	Each	
18	30	Starter (with one year Guarantee)	No.	
19	30	Rotor (with one year Guarantee)	No.	
20	35	Carbon Housing	No.	
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	
22	45	Oil Seal	No.	
23	45	Oil Seal Steel Bush	No.	
24	45	D.O Bearing	No.	
25	210	Steel Bush	No.	
26	20	Allen Screw	No.	
27	45	Pump Key (Stainless Steel)	No.	
28	30	Non - return valve (NRV) assembly complete with rubber 'O' Ring	No.	
29	45	Cable Guard	No.	
30	45	Strainer	No.	
31	45	Brass Filter	No.	
32	45	Labour Chargesw (Over Hauling Only)	No.	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	
34	50	Lock Ring	Each	
35	45	Carbon Housing	Each	
36	45	Top Carbon/Ferodo padding	Each	
37	45	Bearing (Gunmetal) Centrifugal Cast Aluminium Bronze, Bearing bush	Each	
38	45	Circclips	Each	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	
42	440.00	Threading of GI Pipes 50mm Dia	No's	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's	

Kuvempu nagar 4th cross dead end.

Log Book					
Location:				Date: 23/10/22	
Maintenance of water supply Existing borewells at Bellahalli, Thirumenahalli and Chokkannahalli Village Surrounding area in Ward No. 05, Byatarayanapura Sub Division					
item No	Approved Quantity	Description	Unit	used	Remarks
1	2800	Labour Charges of lifting of non functioning submersible Pump set along with cable and GI Pipes	Each Length	60	
2	45	Transportation of pumping machineries	Each	1	
3	7	Rewinding of Submersible Pump Sets 10 HP	No.		
4	8	Rewinding of Submersible Pump Sets 7.5 HP	No.		
5	15	Rewinding of Submersible Pump Sets 12.5 HP	No.	1	
6	15	Rewinding of Submersible Pump Sets 15.0 HP	No.		
7	140	Pump Bowls	No.		
8	45	Intermediate Piece (I.P) With IP Leaded Bronxe bush	No.	1	
9	45	Upper Flange	No.	1	
10	45	Lower Housing	No.	1	
11	90	Guide vane	No.	2	
12	45	Impeller Shell moulded with aluminium Bronze)	No.	1	
13	45	Discharge outlet (D.O) Bearing D.O Steel Bush P.	No.	1	
14	30	Pump shaft made out of stainless steel Centreless ground with key way (upto 8 stages)	No.	1	
15	45	Pump Couping (Stainless Steel)	No.	1	
16	60	Stud and Nuts	Each		
17	30	Motor Base With Pin	Each		
18	30	Starter (with one year Guarantee)	No.		
19	30	Rotor (with one year Guarantee)	No.		
20	35	Carbon Housing	No.		
21	45	Thrust bearing block assembly complete with Segment bearing pad	No.	1	
22	45	Oil Seal	No.	1	
23	45	Oil Seal Steel Bush	No.	1	
24	45	D.O Bearing	No.	1	
25	210	Steel Bush	No.	1	
26	20	Allen Screw	No.		
27	45	Pump Key (Stainless Steel)	No.	1	
28	30	Non – return valve (NRV) assemlly complete with rubber 'O' Ring	No.		
29	45	Cable Guard	No.	1	
30	45	Strainer	No.	1	
31	45	Brass Filter	No.	1	
32	45	Labour Chargesw (Over Hauling Only)	No.	1	
33	45	Re-erection charges of pumping machineries including overhauling and pointing	Each	1	
34	50	Lock Ring	Each		
35	45	Carbon Housing	Each	1	
36	45	Top Carbon/Ferodo padding	Each	1	
37	45	Bearing (Gunmetal) Centrifugal) Cast Aluminium Bronxe, Beaing bush	Each	1	
38	45	Circillps	Each	1	
39	90.00	Supplying and fixing of Porcelain fuse channel with cut out on existing wooden / panel using necessary nuts, bolts and washer etc., complete	No.	3	
40	440.00	Threading of GI Pipes 50mm Dia			
42	45.00	Supplying and fixing MCB	No's	1	
48	10	Supplying & delivery of brand 50mm Gate Valve.	No's		

[Signature]
ಬಿ.ಎಂ.ಪಿ. ಪಾಟೀಲರವರು
ಬಿ.ಎಂ.ಪಿ. ಪಾಟೀಲರವರು ಉಪ ವಿಭಾಗ

[Signature]
ಬಿ.ಎಂ.ಪಿ. ಪಾಟೀಲರವರು
ಬಿ.ಎಂ.ಪಿ. ಪಾಟೀಲರವರು ಉಪ ವಿಭಾಗ
ಬಿ.ಎಂ.ಪಿ. ಪಾಟೀಲರವರು